



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|--|
| Alert number | A12/00601/20 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Subaru |
| Name | Legacy, Outback, Impreza |
| Type / number of model | Type-approval numbers: e1*2001/116*0438*03, e1*2001/116*0438***, e1*2001/116*0228*10 |
| Company recall code | |
| Production dates | The affected vehicles were manufactured between 2008 and 2010 (Impreza) , between 2004 and 2009 (Legacy, Outback) |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car under Subaru recall code: SRT239. |
| Country of origin | Japan |
| Alert submitted by | Belgium |
| Counterfeit * | UNKNOWN |
| Risk type | Injuries |
| Technical defect | The fuel pump harness connector can overheat and melt, causing the fuel pump to become inoperative. As a result, the engine will stall or will not be able to start, increasing the risk of an accident. / |
| Risk | |
| Measures adopted by notifying country | Recall of the product from end users |
| Company recall page: | https://www.subaru.be |
| Products were found and measures were taken also in | Denmark, Estonia, Greece, Ireland, Luxembourg, Slovakia |
| Images | No pictures are available |