



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|--|
| Alert number | A12/0302/18 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Indian Motorcycles |
| Name | Roadmaster |
| Type / number of model | Unknown |
| Batch number / Barcode | Motorcycles built between 06/06/2014 and 27/07/2017. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle |
| Country of origin | United States |
| Alert submitted by | United Kingdom |
| Risk type | Injuries |
| Technical defect | Water may enter a rear light wiring harness and cause corrosion. |
| Risk | Corroded wires may cause erratic operation of the rear and brake lights, leading to an accident. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Greece, Sweden, The Netherlands |
| Images | No pictures are available |