



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0094/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Motorcycles
<b>Brand</b>	BMW
<b>Name</b>	C 600 Sport / C 650 GT
<b>Type / number of model</b>	Types: K18, K19 EC type approval: e1*2002/24*0552
<b>Batch number / Barcode</b>	Affected vehicles manufactured between 9.2.2011 and 15.7.2015.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Motorcycle.
<b>Country of origin</b>	Germany
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Risk</b>	The positioning of the chafer can cause damage to the front brake hose and lead to a loss of brake fluid. This can reduce brake performance and could lead to accidents.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Croatia, Denmark, Finland, Greece, Ireland, Malta, Norway, Portugal, Slovakia, Slovenia, Spain, Sweden, The Netherlands, United Kingdom
<b>Images</b>	No pictures available