



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---------------------------------------|--|
| Alert number | 0113/05 |
| Category | Electrical appliances and equipment |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | |
| Brand | |
| Name | |
| Type / number of model | |
| Batch number / Barcode | |
| OECD Portal Category | |
| Description | Electric steam iron "Eurolux" (SS1-10-01). |
| Country of origin | Unknown |
| Alert submitted by | Hungary |
| Risk type | Electric shock |
| Risk | Risk of electric shock. Insufficient electric resistance and missing thermal protection device, under certain circumstances breakdown can occur between accessible metal parts and live parts and the iron can catch fire, emit smoke and deform; incompliant plug. The iron does not comply with the Low Voltage Directive and the relevant European standards. |
| Measures adopted by notifying country | Placing on the market prohibited by the authorities. |
| Images | |