



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	1677/10
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car - Legend
Brand	Honda
Name	
Type / number of model	Legend (model code: KB1)
Batch number / Barcode	
OECD Portal Category	
Description	The recall concerns certain 2005, 2006 and 2007 model year vehicles, manufactured between 23 December 2005 and 6 February 2007 and within the VIN range from JHMKB1***7C200006 to JHMKB1***7C204817.
Country of origin	Japan
Alert submitted by	Greece
Risk type	Injuries
Risk	The product poses a risk of injuries (accident) because during regular brake fluid replacement or brake bleeding operations, it may be possible for a seal in the brake master cylinder to become deformed resulting in a small brake fluid leak. If the brake fluid level reduces significantly, the brake warning light and low brake fluid warning light will be activated in the instrument panel. If the vehicle is continued to be driven in this condition, the brake pedal stroke will gradually increase. Finally, if the above symptoms are ignored, one of the brake circuits may fail. Although the remaining circuit provides sufficient brake force to stop the vehicle, the stopping distance will increase.
Measures adopted by notifying country	Voluntary corrective actions taken by the importer.
Products were found and measures were taken also in	Denmark, Germany, Bulgaria, The Netherlands, Iceland, Slovenia, Finland, Ireland, Hungary, Sweden
Images	No pictures are available