



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00415/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger van / Light commercial vehicle
Brand	Mercedes-Benz
Name	Sprinter
Type / number of model	Type-approval numbers: e1*2001/116*0354*22, *23, *0424*15, e1*2007/46*0296*11, *12, *0301*18, *19, *0304*06, *0305*11, *1760*00, *01, *1762*00, *01, Types: 906AC35, 906AC35/4X4, 906BB50, 906BB35, 906BB35/4x4 906BB50/4x4, KL3A4, KL3A5
Company recall code	VS3HELI (8292253)
Production dates	The affected vehicles were manufactured between 8 February and 19 June 2019.
OECD Portal Category	77000000 - Automotive
Description	Passenger van / Light commercial vehicle under Mercedes-Benz recall code: VS3HELI (8292253).
Country of origin	Germany
Alert submitted by	Germany
Counterfeit *	<b>NO</b>
Risk type	Injuries
Technical defect	A defect in the control-unit software of the body control module may cause the rear lights to fail or to be lit too weakly if the light selector switch is operated quickly. This may prevent subsequent traffic from detecting the vehicle, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Denmark, Estonia, Finland, Greece, Hungary, Iceland, Ireland, Luxembourg, Poland, Portugal, Slovenia, Sweden
Images	No pictures are available