



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01063/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	VOLVO
Name	S80, S60, V70, XC70, S60cc, V60, XC60, V60cc, V40, V40cc
Type / number of model	S60: e9*2007/46*0023*14 – e9*2007/46*0023*25, S60cc: e9*2007/46*0023*21 – e9*2007/46*0023*25, V40: e4*2001/116*0076*33 – e4*2001/116*0076*40, V40cc: e4*2001/116*0076*33 – e4*2001/116*0076*40, V60: e9*2007/46*0023*14 – e9*2007/46*0023*25, V60cc: e9*2007/46*0023*21 – e9*2007/46*0023*25, V70: e9*2001/116*0065*24 – e9*2001/116*0065*28, XC60: e9*2001/116*0068*16 – e9*2001/116*0068*24, XC70: e9*2001/116*0065*24 – e9*2001/116*0065*28, S80: e9*2001/116*0057*26 – e9*2001/116*0057*31
Company recall code	R10026, R10027, R10028, R10030
Production dates	The affected vehicles were manufactured between 2014 and 2018.
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Sweden
Alert submitted by	Belgium
Counterfeit *	NO
Risk type	Fire
Technical defect	Air bubbles may remain in the engine cooling system when filling coolant. This can cause insufficient cooling and damage the engine, increasing the risk of fire in the engine compartment. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Denmark, Finland, Greece, Iceland, Ireland, Ireland, Ireland, Luxembourg, Malta, Poland, Portugal, Romania, Romania, Romania, Slovakia, Slovenia, Sweden
Images	No pictures are available