



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1265/14
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Land Rover
Name	Range Rover and Range Rover Sport
Type / number of model	Range Rover 3.0 Litre TDV6, Range Rover 4.4 Litre SDV8 and Range Rover Sport 3.0 Litre V6 Diesel.
Batch number / Barcode	Range Rover (3.0 Litre and 4.4 Litre) - SALGA2KEXDA000001 to SALGA2JE9DA110085. Vehicles built between 09/03/2012 and 22/01/2013. , Range Rover Sport - SALWA2PF1EA000001 to SALWA2PE9EA000061. Vehicles built between 26/11/2012 and 23/01/2014.
OECD Portal Category	77000000 - Automotive
Description	Passenger cars.
Country of origin	United Kingdom
Alert submitted by	United Kingdom
Risk type	Fire
Risk	An internal fault can create a short circuit within the fan control module which may lead to overheating of the insulation and ultimately fire within the engine bay. This may happen with the engine switched off and possibly when the vehicle is unattended.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Ireland, Germany, Slovenia, The Netherlands, Bulgaria, Finland, Sweden, The Netherlands, Sweden
Images	No pictures are available