



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|--|
| Alert number | A12/1574/19 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | BMW |
| Name | S 1000 RR |
| Type / number of model | - EC-type approval number: e1*168/2013*00091; - Type: (0E21/0E23); - Model year: 2018 to 2019; |
| Batch number / Barcode | The affected vehicles were manufactured between 05.09.2018 and 27.08.2019. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle under BMW Recall code: 00 00 17 06 00. |
| Country of origin | Germany |
| Alert submitted by | Portugal |
| Risk type | Injuries |
| Technical defect | The strength of the material of the inlet and outlet hoses in the oil cooler is inadequate. |
| Risk | Consequently cracks might build at the connection between oil hose and oil pipe, leading oil to leak on the rear wheel, increasing the risk of accident. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Bulgaria, Estonia, Finland, Germany, Ireland, Luxembourg, Poland, Slovenia, Sweden |
| Images | No pictures are available |