



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0430/15
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Nissan
<b>Name</b>	Micra
<b>Type / number of model</b>	Micra (K13) fitted with 1.2L supercharged petrol engine.
<b>Batch number / Barcode</b>	Production dates: 25/10/2010 - 27/02/2015.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	India
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	Due to an Engine Control Module (ECM) software error, under certain very limited engine start conditions, the ECM may set an incorrect engine throttle valve position. As a result, at engine speeds in excess of 3600 rpm, the vehicle may briefly accelerate unexpectedly.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users
<b>Products were found and measures were taken also in</b>	Croatia, Denmark, Hungary, Norway, Slovakia, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available