



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0471/15
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Renault
<b>Name</b>	Capture
<b>Type / number of model</b>	e2*2001/116*0327* Types: J5AL, J5A2, J5J5, J5MA, J5MH, J5MW, J5M0, J5M6.
<b>Batch number / Barcode</b>	Production period: from beginning of production (January 2013) until 07/11/2014.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	Spain
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	Due to wrong assembly of the under-wing plastic protectors, the front flexible brake hose could be damaged resulting in a slow brake fluid leak or sudden bursting of the flexible hose. This could lead to long brake pedal travel and loss of braking efficiency.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Denmark, Finland, Germany, Greece, Hungary, Iceland, Ireland, Norway, Slovakia, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available