



## Rapid Alert System for dangerous non-food products

|  |   |
|--|---|
| <b>Alert number</b>  | A12/0509/16   |
| <b>Category</b>  | Motor vehicles  |
| <b>Risk level</b>  | Serious risk  |
| <b>Product user</b>  | Consumer  |
| <b>Product</b>   | Passenger car   |
| <b>Brand</b>   | Nissan  |
| <b>Name</b>  | NV200, e-NV200 and X-Trail  |
| <b>Type / number of model</b>                              | NV200 (M20), e-NV200 (MEO) and X-Trail (T32)  |
| <b>Batch number / Barcode</b>                              | Model year: NV200 (M20) 2009-2016; e-NV200 (MEO) 2014-2016; X-Trail (T32) 2014-2016   |
| <b>OECD Portal Category</b>                                | 77000000 - Automotive   |
| <b>Description</b>   | Passenger car   |
| <b>Country of origin</b>                                   | Japan, Spain  |
| <b>Alert submitted by</b>                                  | Greece  |
| <b>Risk type</b>   | Injuries  |
| <b>Risk</b>  | The outer tube of the gas strut for the rear door may corrode and crack, resulting in the loss of the pressurized gas inside the gas strut. The gas strut would consequently be unable to support the opening of the rear door and could detach from the vehicle during operation of the rear door. |
| <b>Measures adopted by notifying country</b>               | <b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)   |
| <b>Products were found and measures were taken also in</b> | Bulgaria, Croatia, Denmark, Finland, Malta, Norway, Portugal, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom   |
| <b>Images</b>  | No pictures available   |