



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0561/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Van
<b>Brand</b>	Renault
<b>Name</b>	Master
<b>Type / number of model</b>	Master 3. Type: MA, MB, VB, VD, ML; EC type-approval: e2*2007/46*0016*, e2*2007/46*0019*, e2*2007/46*0049*, e2*2007/46*0050*, e2*2007/46*0022*
<b>Batch number / Barcode</b>	Vehicles with an M9T engine, produced between September 2015 and October 2015, are affected.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Van.
<b>Country of origin</b>	France
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Risk</b>	An oil hose may be incorrectly crimped. If the oil hose becomes completely detached, oil could escape, run on the road and endanger following vehicles.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Denmark, Ireland, Portugal, Slovenia, Sweden, The Netherlands, United Kingdom
<b>Images</b>	No pictures available