



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0606/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Renault
<b>Name</b>	Clio
<b>Type / number of model</b>	Clio IV
<b>Batch number / Barcode</b>	e2*2001/116*0327; e2*2007/46*0008. The affected vehicles were manufactured from 15/04/2014 to 06/10/2014 in France and 05/03/2013 to 02/04/2015 in Turkey
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	France, Turkey
<b>Alert submitted by</b>	Malta
<b>Risk type</b>	Injuries
<b>Risk</b>	The front wheel arch may be incorrectly installed. As a result, the brake hose may come into contact with the front wheel arch, causing wear of the brake hose by fretting. If the brake hose breaks and the brake fluid leaks out, the performance of braking could be compromised.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Denmark, Greece, Norway, Slovakia, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available