



Rapid Alert System for dangerous non-food products

Alert number	A12/0615/17
Category	Motor vehicles
Risk level	Serious risk
Product user	Professional
Product	Lorry
Brand	Mitsubishi
Name	FUSO Canter
Type / number of model	Type approval numbers: e4*2007/46*0379*00, e4*2007/46*0380*00, E4*715/2007*630/2012M*0407*00, e4*715/2007*630/2012M*0408*00, e4*595/2009*64/2012A*0003*00 Types: FE4P10-01, FE4P10-02
Batch number / Barcode	The vehicles affected were manufactured between 4.7.2009 and 18.12.2013.
OECD Portal Category	77000000 - Automotive
Description	Lorry
Country of origin	Portugal
Alert submitted by	Germany
Risk type	Fire, Injuries
Risk	The fuel return pipe is insufficiently designed against chemicals, paints, soap or fats used by bodywork manufacturers or in cleaning. The chemicals cause the hoses to swell, which could cause them to break free of their connection, causing fuel to leak out. In the worst case, a fire could occur.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Poland, Portugal, The Netherlands
Images	No pictures available