



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0620/17
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Nissan
<b>Name</b>	Murano
<b>Type / number of model</b>	Japanese production: EC type approval: e1*2001/116*0478; Russian production: E-RU.MT02.B.00026; Type: Z51
<b>Batch number / Barcode</b>	The vehicles affected were manufactured between 2013 and 2015.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	Japan, Russian Federation
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Fire, Injuries
<b>Risk</b>	A power steering pressure hose can break. This results in leakage of power steering fluid, which can cause power steering to fail and possibly also cause a fire.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Poland, Slovakia, The Netherlands
<b>Images</b>	No pictures available