



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0740/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Renault
<b>Name</b>	Kangoo
<b>Type / number of model</b>	Kangoo II (X61); Types: FW0Z, FW06, FW08 and KW12. EC type approvals: e2*2001/116*0364*37; e2*2007/46*0006*32; e2*2007/46*0089*08
<b>Batch number / Barcode</b>	The affected vehicles have been manufactured between 23 November and 27 November 2015
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger cars.
<b>Country of origin</b>	France
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	The mounting screw of the rear left-hand seat belt return (second row seats) has been incorrectly tightened and could become loose, leading to a loss of protection in case of an impact.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Croatia, France, Germany, Norway, United Kingdom
<b>Images</b>	No pictures available