



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0754/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Mercedes-Benz
<b>Name</b>	E-Class
<b>Type / number of model</b>	Type approval number: e1*2007/46*1666*02 -*05 Type: R1EC
<b>Batch number / Barcode</b>	The vehicles in question were manufactured between April 2017 and October 2017.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	Germany
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Fire, Injuries
<b>Technical defect</b>	The seals on the front doors around the window may allow water to enter the inner door area causing damage to the door control unit.
<b>Risk</b>	As a result, the pinch protection on the electric window regulators could be impaired or there could be a short circuit leading to a fire.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Images</b>	No pictures available