



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0848/15
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Renault
<b>Name</b>	Twingo
<b>Type / number of model</b>	Twingo III; type approval: e*2007/46*0457
<b>Batch number / Barcode</b>	The affected vehicles were manufactured since the start of manufacturing to 30/10/2014.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	France
<b>Alert submitted by</b>	Greece
<b>Risk type</b>	Injuries
<b>Risk</b>	The welds of the bracket of the anti-roll bar rod on the front shock absorber could rupture which would lead to degradation of the handling of the vehicle during cornering.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users
<b>Products were found and measures were taken also in</b>	Croatia, Denmark, Germany, Hungary, Ireland, Portugal, Slovenia, The Netherlands, United Kingdom
<b>Images</b>	No pictures available