



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0870/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Van
<b>Brand</b>	Mercedes-Benz
<b>Name</b>	Sprinter
<b>Type / number of model</b>	Type-approval number: e1*2007/46*0294*, *0300*, *0301*, *1762* Type: 906BA50, 906BA35, 906BB35, KL3A5
<b>Batch number / Barcode</b>	The vehicles in question were manufactured between 1/01/2018 and 27/03/2018.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Van
<b>Country of origin</b>	Germany
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Technical defect</b>	The seat height adjuster on the front seats might be inadequately assembled.
<b>Risk</b>	This could result in uncontrolled movement of the seats in the event of a rear collision.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Finland, Poland, The Netherlands
<b>Images</b>	No pictures available