



## Safety Gate: Rapid Alert System for dangerous non-food products

|   |   |
|---|---|
| Alert number  | A12/0870/18   |
| Category  | Motor vehicles  |
| Type of alert                                       | Products with serious risks   |
| Product user  | Consumer  |
| Product   | Van   |
| Brand   | Mercedes-Benz   |
| Name  | Sprinter  |
| Type / number of model                              | Type-approval number: e1*2007/46*0294*, *0300*, *0301*, *1762* Type: 906BA50, 906BA35, 906BB35, KL3A5 |
| Batch number / Barcode                              | The vehicles in question were manufactured between 1/01/2018 and 27/03/2018.                          |
| OECD Portal Category                                | 77000000 - Automotive   |
| Description   | Van   |
| Country of origin                                   | Germany   |
| Alert submitted by                                  | Germany   |
| Risk type   | Injuries  |
| Technical defect                                    | The seat height adjuster on the front seats might be inadequately assembled.                          |
| Risk  | This could result in uncontrolled movement of the seats in the event of a rear collision.             |
| Measures adopted by notifying country               | Recall of the product from end users  |
| Products were found and measures were taken also in | Finland, Poland, The Netherlands  |
| Images  | No pictures are available   |