



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0877/15
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Infiniti
<b>Name</b>	Q50, Q70
<b>Type / number of model</b>	Types: V37, Y51; type-approval numbers: e13*2007/46*1378*00, e13*2007/46*1148*00
<b>Batch number / Barcode</b>	Vehicles produced between 15.4.2014 and 25.12.2014 are affected.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	Japan
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Risk</b>	Because of a faulty gasket on the timing chain tensioner, motor oil may leak out and drip onto the road leading to a skid risk for other road users.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, The Netherlands, United Kingdom
<b>Images</b>	No pictures available