



## Rapid Alert System for dangerous non-food products

|  |  |
|--|--|
| <b>Alert number</b>  | A12/0955/16  |
| <b>Category</b>  | Motor vehicles   |
| <b>Risk level</b>  | Serious risk   |
| <b>Product user</b>  | Consumer   |
| <b>Product</b>   | Passenger car  |
| <b>Brand</b>   | Renault  |
| <b>Name</b>  | Espace V, Megane IV and Talisman   |
| <b>Type / number of model</b>                              | EC-type approval numbers: E2*2007/46*0470*03 (Espace V); E2*2007/46*0546*02 (Megane IV); E2*2007/46*2969*02 and E2*2007/46*2969*03 (Talisman)  |
| <b>Batch number / Barcode</b>                              | Vehicles equipped with ABS-ESC hydraulic unit assembled between 12/02/2016 and 03/03/2016 or 17/03/2016 and 12/04/2016 and fitted on Espace V and Talisman, manufactured between 19/02/2016 and 20/04/2016, or Megane IV, manufactured between 26/02/2016 and 22/04/2016, are affected.            |
| <b>OECD Portal Category</b>                                | 77000000 - Automotive  |
| <b>Description</b>   | Passenger car.   |
| <b>Country of origin</b>                                   | France   |
| <b>Alert submitted by</b>                                  | Portugal   |
| <b>Risk type</b>   | Injuries   |
| <b>Risk</b>  | The hydraulic unit of the anti-lock braking /electronic stability control system may have been contaminated with plastic or metallic particles during the manufacturing process. This could lead to a decrease in the efficiency of the anti-lock braking and/or the electronic stability control. |
| <b>Measures adopted by notifying country</b>               | <b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)  |
| <b>Products were found and measures were taken also in</b> | Bulgaria, Croatia, Denmark, Finland, Germany, Norway, Slovakia, Slovenia, Sweden, The Netherlands  |
| <b>Images</b>  | No pictures available  |