



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0956/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Dacia
<b>Name</b>	Dokker and Lodgy
<b>Type / number of model</b>	EC type approval: E2*2001/116*0314*79
<b>Batch number / Barcode</b>	Vehicles equipped with ABS-ESC hydraulic unit assembled between 12/02/2016 and 03/03/2016 or between 17/03/2016 and 12/04/2016 and possibly fitted on Dacia Dokker, manufactured between 26/02/2016 and 21/04/2016, and Dacia Lodgy, manufactured between 26/02/2016 and 22/04/2016, are affected.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	Morocco
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	The hydraulic unit of the anti-lock braking /electronic stability control system may have been contaminated with plastic or metallic particles during the manufacturing process. This could lead to a decrease in the efficiency of the anti-lock braking and/or the electronic stability control.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Denmark, Finland, Germany, Iceland, Slovakia, Slovenia, Sweden
<b>Images</b>	No pictures available