



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/1226/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Van
<b>Brand</b>	Nissan
<b>Name</b>	Primastar
<b>Type / number of model</b>	Primastar (X83)
<b>Batch number / Barcode</b>	Vehicles manufactured between 25 September 2012 and 14 December 2013.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Van
<b>Country of origin</b>	France
<b>Alert submitted by</b>	Spain
<b>Risk type</b>	Injuries
<b>Risk</b>	There may be cracks in the metallic structure of the steering wheel and as a consequence the structural resistance of the steering wheel may be compromised. The steering wheel could break and become detached from the steering column, resulting in a loss of steering control.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Denmark, Germany, Ireland, Norway, Sweden
<b>Images</b>	No pictures available