



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00127/21
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	YAMAHA
Name	FJR1300, MT-10, MT-09, NIKEN, TMAX, XT1200
Type / number of model	Type-approval numbers: e13*2002/24*0574, e13*168/2013*00001, e13*168/2013*00008, e13*168/2013*00286, e13*168/2013*00332, e13*168/2013*00047, e13*168/2013*00660, e13*2002/24*0653, e13*168/2013*00062, Types: RP23, RP28, RN45, RN57, RN58, SJ14, SJ18, DP04, DP07
Company recall code	
Production dates	The affected vehicles were manufactured between 2012 and 2020.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Germany
Counterfeit *	NO
Risk type	Injuries
Technical defect	Due to oxidation, an electrical fault may occur in the brake-light switch that is fitted on the handlebar brake lever. This may lead to malfunctioning of the cruise control, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Greece, Poland, Romania, Slovenia, Sweden
Images	No pictures are available