



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01179/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Honda
Name	CBR1000 STL/SPL
Type / number of model	e4*168/2013*00126*00
Company recall code	3LD
Production dates	The affected vehicles were manufactured between 1st June 2020 and 16th July 2020.
OECD Portal Category	77000000 - Automotive
Description	Model year: 2020; VIN Range: CBR1000STL (from JH2SC82AXLK000057 to JH2SC82A1LK000626); CBR1000SPL (from JH2SC82B2LK000062 to JH2SC82B1LK001722).
Country of origin	Japan
Alert submitted by	Portugal
Counterfeit *	NO
Risk type	Injuries
Technical defect	The oil pan bolts may not be tightened to the required torque during the post-production inspection which can cause them to become loose or fall out. As a result, oil contamination can spread to the rear wheel, causing the motorcycle to lose traction. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Poland, Slovakia
Images	No pictures are available