



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0095/17
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	DACIA
<b>Name</b>	Logan II, Sandero II
<b>Type / number of model</b>	e2*2001/116*0314*80, e2*2007/46*0030*38
<b>Batch number / Barcode</b>	The vehicles concerned were manufactured between 21/09/2016 and 05/10/2016.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	France
<b>Alert submitted by</b>	France
<b>Risk type</b>	Injuries
<b>Risk</b>	The front right brake caliper's clip could break as a result of the cylinder rupturing. This could reduce the efficiency of the vehicle's braking system in the case of emergency braking.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Denmark, Finland, Greece, Poland, Portugal, Slovakia, Slovenia, Sweden
<b>Images</b>	No pictures available