



## Rapid Alert System for dangerous non-food products

|  |   |
|--|---|
| <b>Alert number</b>  | A12/0124/15   |
| <b>Category</b>  | Motor vehicles  |
| <b>Risk level</b>  | Serious risk  |
| <b>Product user</b>  | Consumer  |
| <b>Product</b>   | Passenger car   |
| <b>Brand</b>   | Infiniti  |
| <b>Name</b>  | Q50 Hybrid, Q70 Hybrid  |
| <b>Type / number of model</b>                              | Type: V37, Y51 EC type-approval: e13*2007/46*1378*00, e13*2007/46*1148*00                             |
| <b>Batch number / Barcode</b>                              | Vehicles manufactured between 2010 and 2014 are affected.   |
| <b>OECD Portal Category</b>                                | 77000000 - Automotive   |
| <b>Description</b>   | Passenger car.  |
| <b>Country of origin</b>                                   | Japan   |
| <b>Alert submitted by</b>                                  | Germany   |
| <b>Risk type</b>   | Injuries  |
| <b>Risk</b>  | The transmission housing may develop cracks and be destroyed. The drive motor may then suddenly fail. |
| <b>Measures adopted by notifying country</b>               | <b>Measures taken by economic operators:</b> Recall of the product from end users                     |
| <b>Products were found and measures were taken also in</b> | Bulgaria, Spain, The Netherlands  |
| <b>Images</b>  | No pictures available   |