



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0302/18
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Motorcycle
Brand	Indian Motorcycles
Name	Roadmaster
Type / number of model	Unknown
Batch number / Barcode	Motorcycles built between 06/06/2014 and 27/07/2017.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	United States
Alert submitted by	United Kingdom
Risk type	Injuries
Technical defect	Water may enter a rear light wiring harness and cause corrosion.
Risk	Corroded wires may cause erratic operation of the rear and brake lights, leading to an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Greece, Sweden, The Netherlands
Images	No pictures are available