



## Rapid Alert System for dangerous non-food products

|  |   |
|--|---|
| <b>Alert number</b>  | A12/0815/17   |
| <b>Category</b>  | Motor vehicles  |
| <b>Risk level</b>  | Serious risk  |
| <b>Product user</b>  | Consumer  |
| <b>Product</b>   | Passenger car   |
| <b>Brand</b>   | Renault   |
| <b>Name</b>  | Talisman  |
| <b>Type / number of model</b>                              | e11*2007/46*2969 ext 00 to 03   |
| <b>Batch number / Barcode</b>                              | Vehicles manufactured since the start of manufacturing until 21/04/2016.  |
| <b>OECD Portal Category</b>                                | 77000000 - Automotive   |
| <b>Description</b>   | Passenger car.  |
| <b>Country of origin</b>                                   | France  |
| <b>Alert submitted by</b>                                  | Portugal  |
| <b>Risk type</b>   | Injuries  |
| <b>Risk</b>  | The brake caliper/brake disk combination may be inadequate. As a consequence, the inadequate friction surface between the brake disk and the brake could affect the brake efficiency and balance with a possibility of pulling (right or left) during braking, or even a risk of decreasing braking efficiency of the vehicle without warning on the dashboard. |
| <b>Measures adopted by notifying country</b>               | <b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)   |
| <b>Products were found and measures were taken also in</b> | Bulgaria, Croatia, Denmark, Finland, Germany, Poland, Slovakia, Slovenia, The Netherlands   |
| <b>Images</b>  | No pictures available   |