



Rapid Alert System for dangerous non-food products

Alert number	A12/0853/18
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Van
Brand	Mercedes-Benz
Name	Sprinter
Type / number of model	Type-approval numbers: e1*2001/116*0353, 0354, 0424, e1*2007/46*0279*, 0280, 0294 - 0301, 0304, 0305, 0307 - 0312, 0566 types: see section 8
Batch number / Barcode	The vehicles affected were produced between 11/09/2017 and 11/10/2017.
OECD Portal Category	77000000 - Automotive
Description	Van
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Technical defect	There are missing welding points on the front side wall.
Risk	This may increase the risk of injury to the occupants of the vehicle in the event of an accident.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Products were found and measures were taken also in	Poland, Sweden, The Netherlands
Images	No pictures available