



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0976/17
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Motorcycle
Brand	Harley-Davidson
Name	FLHX, FLHXS, FLTRX, FLTRXS, FLHTCU, FLHR, FLHRC, FLHRXS, FLHP, FLHTP
Type / number of model	Type-approval numbers: e4*168/2013*00016; Types: FL3
Batch number / Barcode	The vehicles concerned were produced between 2 June 2016 and 9 May 2017.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	United States
Alert submitted by	Germany
Risk type	Injuries
Risk	A clamp on the oil-cooling system may have been incorrectly fitted. This could result in the oil cooler line becoming detached and sudden loss of engine oil. Loss of engine oil could lead to a skid risk for following vehicles as well as the motorcyclist.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Greece, Norway, The Netherlands
Images	No pictures are available