



Rapid Alert System for dangerous non-food products

| | |
|--|---|
| Alert number | A12/1343/16 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Renault |
| Name | Espace, Scenic |
| Type / number of model | Espace V : e2*2007/46*0470 ext. 00 to 03 Scenic III : e2*2001/116*0379 ext. 00 to 43. |
| Batch number / Barcode | Manufactured until 25.5.2016 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car |
| Country of origin | France |
| Alert submitted by | France |
| Risk type | Injuries |
| Risk | The rear screws on the front seat runners were not tightened. In the event of an accident or sudden braking, the front seats may tip forwards owing to the poor attachment or breakage of the seat runner's fittings. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) |
| Products were found and measures were taken also in | Croatia, Denmark, Estonia, Germany, Ireland, Poland, Portugal, Slovakia, Slovenia, Sweden, United Kingdom |
| Images | No pictures available |