



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|---|
| Alert number | A12/1387/18 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Indian Motorcycle Company |
| Name | Scout, Scout Sixty, Scout Bobber |
| Type / number of model | Model year 2017 & 2018 |
| Batch number / Barcode | The vehicles affected were manufactured between 10 January 2017 and 07 May 2018. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle. |
| Country of origin | United States |
| Alert submitted by | United Kingdom |
| Risk type | Injuries |
| Technical defect | There might be air in the brake liquid circuit of the ABS system. |
| Risk | This can cause a decrease in the performance of the brake, which could increase the risk of accident. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Estonia, Germany, Ireland, Poland, Slovakia, Sweden |
| Images | No pictures are available |