



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/1524/17
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Peugeot
<b>Name</b>	4008
<b>Type / number of model</b>	e2*2007/46*0115*01, e2*2007/46*0115*02, e2*2007/46*0115*03, e2*2007/46*0115*04
<b>Batch number / Barcode</b>	Manufactured between 24 November 2011 and 12 September 2014
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	France
<b>Alert submitted by</b>	France
<b>Risk type</b>	Injuries
<b>Risk</b>	Water can enter the vent mechanism for the front windscreen-wiper motor. This could result in the windscreen-wiper motor becoming completely blocked because of internal corrosion. Failure of the windscreen-wipers whilst driving in rain would lead to reduced visibility for the driver.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Bulgaria, Estonia, Germany, Slovakia, Sweden
<b>Images</b>	No pictures available