

## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/1769/16
<b>Category</b>	Lighting equipment
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Work light
<b>Brand</b>	Herran
<b>Name</b>	Lámpara de Trabajo
<b>Type / number of model</b>	6232289; 5M
<b>Batch number / Barcode</b>	6923550232896
<b>OECD Portal Category</b>	78000000 - Electrical Supplies
<b>Description</b>	Work light in a transparent plastic bag.
<b>Country of origin</b>	China
<b>Alert submitted by</b>	Spain
<b>Risk type</b>	Burns, Fire
<b>Risk</b>	Nearby surfaces get too hot during normal operation of the light which could cause a fire or burns to the user. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598.
<b>Measures adopted by notifying country</b>	<b>Measures ordered by public authorities:</b> Withdrawal of the product from the market
<b>Images</b>	

