

Vehicle and Motor Bike Inspections - 2012

Type: [Stockshots \[short\]](#) Référence: [I073108](#) Durée: 14:09 Lieu: [Austria](#) | [Brussels](#) | [Germany](#)

This video stockshot shows images of vehicle and motor bike inspections: - Car inspections in Belgium; - Motor bike inspections in Germany; - Mobile inspections for lorries and vans in Austria.



| HEURE | DESCRIPTION | DUREE |
|----------|--|----------|
| 00:00:00 | Credits and title | 00:00:20 |
| 00:00:20 | 1. Car Inspections, Belgium | 00:04:00 |
| 00:00:20 | Title | 00:00:05 |
| 00:00:25 | Vehicules queuing in front of the technical control centre, Brussels, Belgium | 00:00:06 |
| 00:00:31 | Checking vehicules identification: licence plate, chassis number (2 shots) | 00:00:16 |
| 00:00:47 | Checking the breaking system: foot brake, hand brake and parking break (6 shots) | 00:00:55 |
| 00:01:42 | Checking lights: navigation lights, dipped headlights, sidelights, rear lights (4 shots) | 00:00:31 |
| 00:02:13 | Wide shot of the control room | 00:00:08 |
| 00:02:21 | Checking the axle, wheels, tires and suspension (7 shots) | 00:01:04 |

| | | |
|----------|---|----------|
| 00:03:25 | Inspecting a bus and a van (3 shots) | 00:00:25 |
| 00:03:50 | Checking the headlights and tires of a police vehicle (2 shots) | 00:00:20 |
| 00:04:10 | Van leaving the technical control centre | 00:00:10 |
| 00:04:20 | Title | 00:00:05 |
| 00:04:20 | 2. Motor Bike Inspections, Germany | 00:04:37 |
| 00:04:25 | Arrival of a motorbike at the control station for an inspection | 00:00:05 |
| 00:04:30 | Motor bike rider getting off his motor bike and entering the office | 00:00:07 |
| 00:04:37 | Handing over his papers to start the inspection | 00:00:09 |
| 00:04:46 | Employee checking the motor bike rider's papers | 00:00:04 |
| 00:04:50 | Motor bike rider returning to his motor bike, ready to start the inspection | 00:00:15 |
| 00:05:04 | Checking the head lights (2 shots) | 00:00:14 |
| 00:05:18 | Checking the rear lights (3 shots) | 00:00:22 |
| 00:05:41 | Checking head lights on the front of the bike (2 shots) | 00:00:13 |
| 00:05:54 | Checking the chassis number (4 shots) | 00:00:19 |
| 00:06:13 | Handlebars and suspension check (3 shots) | 00:00:20 |
| 00:06:33 | Steering lock (2 shots) | 00:00:08 |
| 00:06:41 | Checking the front wheel - brakes and suspension | 00:00:05 |

| | | |
|----------|--|----------|
| 00:06:46 | Motor bike elevated on a ramp | 00:00:05 |
| 00:06:52 | Checking the ABS | 00:00:05 |
| 00:06:57 | Checking brake calipers (6 shots) | 00:00:28 |
| 00:07:24 | Chain, exhaust pipe | 00:00:05 |
| 00:07:30 | Ramp checking steering (2 shots) | 00:00:13 |
| 00:07:43 | Testing exhaust gasses | 00:00:13 |
| 00:07:55 | Close-up of the test machine measuring emissions | 00:00:07 |
| 00:08:02 | Noise control | 00:00:05 |
| 00:08:07 | Close-up of the test machine measuring sound | 00:00:05 |
| 00:08:12 | Placing new inspection sticker on bike | 00:00:25 |
| 00:08:37 | Signing the documents | 00:00:05 |
| 00:08:42 | Close-up of the official documents | 00:00:05 |
| 00:08:47 | Control officer giving the last document to the biker indicating that the inspection has been successful | 00:00:05 |
| 00:08:52 | Motor bike leaving | 00:00:05 |
| 00:08:57 | 3. Mobile Inspections for Lorries and Vans, Austria | 00:05:12 |
| 00:08:57 | Title | 00:00:05 |
| 00:09:02 | General view of the motorway station Arnoldstein | 00:00:05 |
| 00:09:07 | Close-up of the panel indicating "Arnoldstein" | 00:00:04 |
| 00:09:11 | Arrival of the mobile control lorry | 00:00:09 |

| | | |
|----------|---|----------|
| 00:09:20 | Setting up the mobile testing equipment (6 shots) | 00:00:32 |
| 00:09:53 | Lorry arriving in the control area | 00:00:10 |
| 00:10:03 | Policeman checking the papers of a van (2 shots) | 00:00:10 |
| 00:10:13 | Policeman checking the wheels of a lorry (3 shots) | 00:00:19 |
| 00:10:32 | Positioning the lorry on the control equipment | 00:00:14 |
| 00:10:46 | Checking the lorry's brakes (2 shots) | 00:00:12 |
| 00:10:58 | Arrival of another lorry | 00:00:10 |
| 00:11:08 | Checking the steering controls (3 shots) | 00:00:23 |
| 00:11:31 | Checking the axle (3 shots) | 00:00:38 |
| 00:12:10 | Test results document (5 shots) | 00:00:33 |
| 00:12:43 | Departure of lorry and trailer | 00:00:09 |
| 00:12:52 | Faulty brakes found when testing lorry (7 shots) | 00:00:37 |
| 00:13:29 | Compiling and printing report - lorry is blocked in the control area and the driver goes to the police office (7 shots) | 00:00:34 |
| 00:14:03 | Copyright | 00:00:07 |