




Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---------------------------------------|---|
| Alert number | 0213/08 |
| Category | Electrical appliances and equipment |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Car cabin heater |
| Brand | Osaset |
| Name | |
| Type / number of model | Type: PTC-19 (Osaset), EAN: 6 420617 646080. |
| Batch number / Barcode | |
| OECD Portal Category | |
| Description | Cabin car heater with plastic enclosure and rubber mains cord. |
| Country of origin | China |
| Alert submitted by | Finland |
| Risk type | Electric shock |
| Risk | There is a risk of electric shock due to the fact that there is not sufficient electrical insulation. At the bending test when rotating the complete cable around a mandrel with diameter 32 mm at 35±2 °C temperature, it shows cracks both at the sheath and at the insulation such that the wires of the conductors are accessible. The cable shall withstand the bending test without showing any cracks. The product does not comply with the Low Voltage Directive and the relevant European standard EN 60811. |
| Measures adopted by notifying country | Withdrawal from the market and recall from consumers ordered by the authorities. |
| Images |  |