



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	0701/11
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car "Agila A"
Brand	Opel
Name	
Type / number of model	Vehicles from: 3 G 077226 to 7 G 129308. Production period: from 2003 to 2007
Batch number / Barcode	
OECD Portal Category	
Description	Passenger car
Country of origin	Poland
Alert submitted by	Portugal
Risk type	Fire, Injuries
Risk	Fuel tank corrosion may occur. The paint of the fuel tank can delaminate from the underlying coating and in severe cases this might lead to perforation of the fuel tank resulting in fuel leaks.
Measures adopted by notifying country	Voluntary corrective action taken by the manufacturer
Products were found and measures were taken also in	Germany, Hungary, Sweden, Bulgaria, Slovenia, Spain, The Netherlands, Ireland, United Kingdom
Images	No pictures are available