



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	0929/07
Category	Childcare articles and children's equipment
Type of alert	Products with serious risks
Product user	Consumer
Product	High chair - "Agnieška - 1"
Brand	KLUPŚ@ MEBLE DZIECIĘCE
Name	
Type / number of model	High chair "Agnieška - 1", Gat. I A-B
Batch number / Barcode	
OECD Portal Category	
Description	High chair with soft seat and backrest, there is a tablemat and a crotch belt. The high chair consists of a table and a chair; the table turns 90° angle and chair puts on.
Country of origin	Poland
Alert submitted by	Lithuania
Risk type	Injuries
Risk	The product poses a risk of injuries due to incorrect construction and openings in the access zone, where the fingers or other parts of a child could be entrapped. The product contains the following non-compliances: - the pin with cross-section 7 mm goes into a hole between backrest and hind leg further on 10mm, (further then 10mm shall no to climb), - the assemblage of the high chair uses screw-bolts (screw-bolts can not be used for the assemblage of singly projected parts, when highchair is demountable for transportation or storage), - moving the high chair emerges the openings between crossbar of legs and supporting bar (possibility of injury), - the instructions for safety use in Lithuanian are missing. This product does not comply with the relevant European standards.
Measures adopted by notifying country	Withdrawal from the market ordered by the authorities
Images	