



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A11/0014/19
Category	Motor vehicles
Type of alert	
Product user	Consumer
Product	Passenger Car
Brand	Jaguar
Name	XE, XF
Type / number of model	Type approval numbers: E11*2007/46*2150, E11*2007/46*2981
Batch number / Barcode	Specific vehicles built between 10/10/2014 and 20/11/2018
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	United Kingdom
Alert submitted by	United Kingdom
Risk type	Environment
Technical defect	Certain vehicles fitted with 2.0L Diesel Engines may emit excessive levels of CO2 and may not conform with the certified condition.
Risk	CO2 and other greenhouse gases contribute to global warming pollution. A reduction in CO2 emissions contributes to the EU greenhouse gas reduction targets helping protect the environment. The product does not comply with the Regulation setting emission performance standards for new passenger cars and the Regulation on type approval of motor vehicles with respect to emissions from light passenger and commercial vehicles.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Slovenia
Images	No pictures are available