



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00022/21
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Ducati
Name	Scrambler 1100
Type / number of model	e3*168/2013*00023*01; e49*168/2013*00039*01
Company recall code	CR201
Production dates	
OECD Portal Category	77000000 - Automotive
Description	Ducati Scrambler 1100, Model Years: 2018 - 2021.
Country of origin	Italy
Alert submitted by	Poland
Counterfeit *	UNKNOWN
Risk type	Fire
Technical defect	The exhaust valve cable could contact the main positive battery wire. This can result in an electrical short circuit, increasing the risk of fire. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Estonia, Greece, Sweden
Images	No pictures are available