



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00128/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Renault
Name	Captur
Type / number of model	Model series: X87, Type-approval numbers: e2*2001/116*0327*87, e2*2001/116*0327*88
Company recall code	0D61
Production dates	The affected vehicles were manufactured between 13 November and 20 December 2018.
OECD Portal Category	77000000 - Automotive
Description	Passenger cars manufactured in Valladolid under Renault recall code: 0D61.
Country of origin	Spain
Alert submitted by	Portugal
Counterfeit *	NO
Risk type	Injuries
Technical defect	The retractor of the front-left seatbelt can be displaced from its housing due to a lack of fixing screws. This can impair the seatbelt's protective function, increasing the risk of injuries in the event of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Ireland, Poland, Sweden
Images	No pictures are available