



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0030/19
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Three-wheeled motorcycle
Brand	Polaris
Name	Slingshot
Type / number of model	Model year 2015 and 2016 Slingshot motorcycles
Batch number / Barcode	Specific vehicles built between 15/05/2014 and 08/10/2015
OECD Portal Category	77000000 - Automotive
Description	Three-wheeled motorcycle
Country of origin	United States
Alert submitted by	United Kingdom
Risk type	Injuries
Technical defect	The backup camera could fail internally and melt the voltage regulator over-mold.
Risk	As a consequence, the circuit fuse may blow, which would inhibit proper tail light function.
Measures adopted by notifying country	Recall of the product from end users
Images	No pictures are available