



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00347/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Renault
Name	Clio, Captur
Type / number of model	Model series: X98, X87 , Type-approval numbers: e2*2001/116*0327*87, e2*2001/116*0327*88, e2*2001/116*0327*89, e2*2007/46*0008*40, e2*2007/46*0008*41, e2*2007/46*0008*42
Company recall code	0D78
Production dates	The affected vehicles were manufactured prior to 24 July 2019.
OECD Portal Category	77000000 - Automotive
Description	Vehicles equipped with H4Bt engines, produced at Bursa, Valladolid and Novo Mesto under Renault recall code: 0D78.
Country of origin	France
Alert submitted by	France
Counterfeit *	NO
Risk type	Fire
Technical defect	The positive terminal of the battery can come into contact with the heat sink on the alternator. This can lead to an electrical short circuit and to increased risk of fire in the engine compartment. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Estonia, Finland, Germany, Greece, Ireland, Sweden
Images	No pictures are available