



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0107/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Ducati
Name	Monster 821, Monster 1200, SuperSport 939
Type / number of model	Unknown
Batch number / Barcode	model year: 2017 - 2019 (Monster 1200; SuperSport), model year: 2018 - 2019 (Monster 821)
OECD Portal Category	77000000 - Automotive
Description	Motorcycle. Recall code: CR168
Country of origin	Italy
Alert submitted by	Poland
Risk type	Injuries
Technical defect	The interference fit between the lever tip pin and the gear shift lever may not perform, which may cause the pin to detach.
Risk	This leads to an increased risk of a crash.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Estonia, Ireland, Slovenia, Sweden, The Netherlands
Images	No pictures are available