



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01122/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	TOYOTA
Name	Hiace, Land Cruiser Prado
Type / number of model	Hiace – frame code GDH306, WMI: JTF, Range by frame number: VDS – VB3AP#; VIS – 080010020, Land Cruiser Prado - frame code GDJ150, WMI: JTE, Range by frame number: VDS – BR8FJ#; VIS – 0K133486-0K137484, Land Cruiser Prado - frame code GDJ155, WMI: JTE, Range by frame number: VDS – CR3FJ#; VIS – 05009583-05009949, Land Cruiser Prado – frame code GDJ150, WMI: JTE, Range by frame number: VDS – BR3FJ#; VIS – 05013668-0K140000, Type-approval number: Individual approval - Hiace , Type-approval number: e6*2007/46*0001*09 - Land Cruiser
Company recall code	19SMD-064
Production dates	Hiace - production period 05.05.2019, Land Cruiser Prado - Production period from 11.03.2019 to 14.05.2019
OECD Portal Category	77000000 - Automotive
Description	Vehicles equipped with diesel engines.
Country of origin	Japan
Alert submitted by	Bulgaria
Counterfeit *	NO
Risk type	Injuries
Technical defect	Due to incorrect instructions for the degree of tightening, the fuel pipe connecting the fuel pump to the main fuel pipe may get loosened by the engine vibrations. As a result, fuel may leak and cause the engine to stall, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Finland, Iceland, Ireland, Slovakia, Slovenia
Images	No pictures are available