



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01866/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	YAMAHA
Name	NMAX125, X-MAX125, X-MAX300, X-MAX400, YZF-R3, MT-03, XSR700, TRACER 700, TENERE 700
Type / number of model	e13*168/2013*00067, e13*168/2013*00164 Types: SH13, SH08, RM11, RM14, RM30, DM07, DM08, SEE6, SH12, SE93, SEC7, RH12, RH07, e13*168/2013*00287, e13*168/2013*00043, e13*168/2013*00003, e13*168/2013*00024, e13*168/2013*00782, e13*168/2013*00648, e13*168/2013*00649, e13*168/2013*00284, e13*168/2013*00241, e13*2002/24*0747,
Company recall code	
Production dates	The affected vehicles were manufactured between 2013 and 2020.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	France
Alert submitted by	Germany
Counterfeit *	<b>NO</b>
Risk type	Injuries
Technical defect	The rear retro-reflector does not properly reflect the light coming from behind the vehicle. As a result, the vehicle would not be sufficiently visible for the following traffic, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Greece, Poland, Slovenia, Sweden
Images	No pictures are available