



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0240/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Kawasaki
Name	ZR900
Type / number of model	Type-approval numbers: e1*168/2013*00043*01, e1*168/2013*00060*00, e1*168/2013*00057*00 types: ZR900B, ZR900D, ZR900C sales name: ZR900
Batch number / Barcode	The vehicles concerned were manufactured in 2018.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle. Company recall code: DAJ04
Country of origin	Japan
Alert submitted by	Germany
Risk type	Injuries
Technical defect	Owing to incorrect installation, the rear wheel brake line and/or the ABS sensor cable can be damaged through contact with the rear wheel.
Risk	This can lead to failure of the rear wheel brake and the ABS, which could lead to an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Estonia, Finland, Hungary, Luxembourg, Slovenia, Sweden, The Netherlands
Images	No pictures are available